



Eastman Chemical Company: Abandoned Steel Pipe Line Rehabilitation

Location: Kingsport, Tennessee

Situation:

This Eastman Chemical Company manufacturing facility wanted to recommission an old and abandoned, 8"-wide, steel pipe line about a mile in length. Cleaning the pipe line did not remove all traces of poisonous chemicals that it used to carry, so the customer researched other solutions.

Solution:

Nu Flow technicians used our patented, blown-in epoxy to line the pipes in-place. This saved the customer from a messy, inconvenient and multi-million-dollar repipe. Nu Pipe's barrier coating will prevent any chemical leaching from the original pipe and is a long-term solution against failures.

